


0400-SC016-A0000-1S02

Machine: TSUGAMI

Type: BW207 – BW208 – BE208Z – BW209Z

Emplacement, N°: T01 - T02 – T11 – T12

Travail sur: Broche principale


Type de travail:  $n_{\max}$: 8000 [rpm] i (n_i / n_o): 1 / 1

Attachement: ER16

Sans refroidissement

Infos:

0400-SC016-A0000-1S02



Machine: TSUGAMI

Type: BW207 – BW208 – BE208Z – BW209Z

Location, N°: T01 - T02 – T11 – T12

Work on: Main spindle

Type of work: 


n_{max} : 8000 [rpm]

i (n_i / n_o): 1 / 1

Attachement: ER 16

Without coolant

Infos:

0400-SC016-A0000-1S02

Maschine: TSUGAMI

Typ: BW207 – BW208 – BE208Z – BW209Z

Position, N°: T01 - T02 – T11 – T12

Arbeit über: Hauptspindel

Arbeitstyp: 


$n_{\max}$: 8000 [rpm]

i (n_i / n_o): 1 / 1

Befestigung: ER 16

Ohne Kühlmittel

Infos:

0400-SC016-A0000-1S02

Macchina: TSUGAMI

Tipo: BW207 – BW208 – BE208Z – BW209Z

Posizione, N°: T01 - T02 – T11 – T12

Lavoro al: Mandrino principale

Tipo di lavoro: 

n_{max} : 8000 [rpm]

$i (n_i / n_o)$: 1 / 1

Atacco: ER 16

Senza refrigerante

Informazioni: