


1000-SC020-RA0000-1S01

Machine: HANWHA

Type: XD38

Emplacement, N°: Upper gang tool post


Travail sur: Broche principale

Type de travail: i (n_i / n_o): 1 / 1

Attachement: ER20

Sans refroidissement

Infos: Angle ajustable +/-45°
(angle réglable +/-15° & 3 plats sur la queue à -30° / 0° / 30°)


1000-SC020-RA0000-1S01

Machine: HANWHA
Type: XD38
Location, N°: Upper gang tool post
Work on: Main spindle
Type of work: 
i (n_i / n_o): 1 / 1
Attachement: ER20

Without coolant

Infos: Adjustable angle +/-45

(adjustable angle +/-15° & 3 flats on tail at -30° / 0° / 30°)

1000-SC020-RA0000-1S01

Maschine: HANWHA
Typ: XD38
Position, N°: Upper gang tool post
Arbeit über: Hauptspindel
Arbeitstyp: 
i (n_i / n_o): 1 / 1
Befestigung: ER20

Ohne Kühlmittel

Infos: Einstellbarer Winkel +/-45°.

(Winkel einstellbar +/-15° & 3 Abflachungen am Schwanz bei -30° / 0° / 30°.